

Certificate of Conformity

Certificate Number: B-S15067471



Holder.....: Tianjin Geneuo Technology Co., Ltd.
Address.....: Technology Avenue South, Jinghai Development Area,
Tianjin City, China
Manufacturer.....: Same As Holder
Product.....: Over Moulding Connector (M8,M12,M16,M23,7/8")
Model No.....: See Appendix A
Technical Data....: DC 24V

The submitted products have been tested by us with the following standard(s) and found to be in compliance with the listed European Directives.

EN 61984:2009

The test results apply only to the particular sample tested and to the specific tests carried out. Technical Report and documentation are at the Holder's disposal.

This certificate applies specifically to the sample investigated in our test reference number only. The CE markings as shown below can be affixed on the product after preparation of necessary technical documentation. Other relevant Directives have to be observed.



Certification Manager
Date: Jun.10, 2015



Company No.07113834



Beide (UK) Product Service Limited

U.K.: Flat 107, 25 Indecon Square, London, United Kingdom

China: 6F, Bldg E, Hourui 3rd Ind Zone, Xixiang, Bao'an Dist, Shenzhen, China

Http://www.szbeide.com E-mail: admin@szbeide.com

EK [^] -*M/...	SK [^] -*M/...	EQK [^] -*M/...	RK [^] -*M/...	SK [^] EZ [^] -*M/...
EZ [^] -*M/...	SZ [^] -*M/...	EQZ [^] -*M/...	RZ [^] -*M/...	EK [^] SZ [^] -*M/...
ELK [^] -*M/...	SLK [^] -*M/...	EQLK [^] -*M/...	RLK [^] -*M/...	SLK [^] ELZ [^] -*M/...
ELZ [^] -*M/...	SLZ [^] -*M/...	EQLZ [^] -*M/...	RLZ [^] -*M/...	SLK [^] EZ [^] -*M/...
EK [^] EZ [^] -*M/...	SK [^] SZ [^] -*M/...	EQK [^] EQZ [^] -*M/...	RK [^] RZ [^] -*M/...	SK [^] ELZ [^] -*M/...
ELK [^] ELZ [^] -*M/...	SLK [^] SLZ [^] -*M/...	EQLK [^] EQLZ [^] -*M/...	RLK [^] RLZ [^] -*M/...	EK [^] SLZ [^] -*M/...
EK4112-0/7	SK3212-0	VA21-024-*M-LV	YWZ [^] -2EK [^]	ELK [^] SZ [^] -*M/...
EZ4112-0/7	SZ3212-0	VA21-110-*M-LV	YWK [^] -2EZ [^]	ELK [^] SLZ [^] -*M/...
EK4112-0/9	SK4212-0	VA21-220-*M-LV	YVZ [^] -2EK [^]	ELK [^] P2-*M/...
EZ4112-0/9	SZ4212-0	VB21-024-*M-LV	YVK [^] -2EZ [^]	EK [^] P2-*M/...
ELK4112-0/7	DNK6-4-*M/...	VB21-110-*M-LV	YSK4-2SZ3-*M-*M/...	SLK [^] P2-*M/...
ELZ4112-0/7	DNLK6-4-*M/...	VB21-220-*M-LV	YSZ4-2SK3-*M-*M/...	SK [^] P2-*M/...
EK5112-0/7	DWZ6-4-*M/...	VBR21-024-*M-LV	YK4-2EZ3-*M-*M/...	ELK [^] P3-*M/...
EZ5112-0/7	DWLZ6-4-*M/...	VBR21-110-*M-LV	YK4-2SZ3-*M-*M/...	ELK [^] P3.1-*M/...
EK5112-0/9	DNK6-6-*M/...	VBR21-220-*M-LV	YZ4-2EK3-*M-*M/...	RLK [^] P2-*M/...
EZ5112-0/9	DNLK6-6-*M/...	VBI21R-024-*M-LV	YZ4-2SK3-*M-*M/...	RK [^] P2-*M/...
ELK5112-0/7	DWZ6-6-*M/...	VBI21R-110-*M-LV	EILZ8-*M/E41	EPK5-*M
ELZ5112-0/7	DWLZ6-6-*M/...	VBI21R-220-*M-LV	FEIK81-*M/E41	EPLK5-*M
MK [^] -*M	DNK14-10-*M/...	GNZ19-11-*M/...	FEIZ81-*M/E41	EPZ5-*M
MZ [^] -*M	DNLK14-10-*M/...	GNLZ19-11-*M/...	RJ45S-*M/E41	EPLZ5-*M
MLK [^] -*M	DWZ14-10-*M/...	GNK19-17-*M/...	TRJ45S-*M/E41	EPK5 EPZ5-*M
MLZ [^] -*M	DWLZ14-10-*M/...	GNLK19-17-*M/...	BRJ45S-*M/E41	EPK5 EPLZ5-*M
MK [^] -*M	MK [^] MLZ [^] -*M	GNZ19-17-*M/...	EIK4-*M/F41	EPLK5 EPZ5-*M
MZ [^] -*M	MLK [^] MLZ [^] -*M	GNLZ19-17-*M/...	EIZ4-*M/F41	EPLK5 EPLZ5-*M
MLK [^] -*M	MK [^] MZ [^] -*M/24	GNK19-19-*M/...	EILK4-*M/F41	MLK [^] MZ [^] -*M
MK [^] -*M/20	GNK12-11-*M/...	GNLK19-19-*M/...	EILZ4-*M/F41	GNLK19-11-*M/...
MZ [^] -*M/20	GNLK12-11-*M/...	GNZ19-19-*M/...	FEIK41-*M/F41	EILK8-*M/E41
MLK [^] -*M/20	GNZ12-11-*M/...	GNLZ19-19-*M/...	FEIZ41-*M/F41	BRJ45S-*M/F41
MLZ [^] -*M/20	GNLZ12-11-*M/...	EIK8-*M/E41	RJ45S-*M/F41	MK [^] MZ [^] -*M
GNK19-11-*M/...	EIZ8-*M/E41	TRJ45S-*M/F41		

Note: ^on behalf of the number of cable core, * on behalf of the cable length,...On behalf of the cable material



Company No.07113834



Beide (UK) Product Service Limited

U.K.: Flat 107, 25 Indescon Square, London, United Kingdom

China: 6F, Bldg E, Hourui 3rd Ind Zone, Xixiang, Bao'an Dist, Shenzhen, China

Http://www.szbeide.com E-mail: admin@szbeide.com